

Oil Field Environmental Incident Summary

Incident: 20170622093654

Date/Time of Notice: 06/22/2017 09:36

Responsible Party: Ballantyne Oil, LLC

Well Operator: BALLANTYNE OIL, LLC

Well Name: GILBERT & PEDERSON CTB

Field Name: NORTH SOURIS

Well File #:

Date Incident: 6/22/2017

Time Incident: 07:35

Facility ID Number: 212496-01

County: BOTTINEAU

Twp: 163

Rng: 77

Sec: 3

Qtr: NW SW

Location Description:

Submitted By: Allen Boettcher

Received By:

Contact Person: Allen Boettcher
PO BOX 167
115 11TH AVE E SUITE 2
BOTTINEAU, ND 58318

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	12	Barrels	12	Barrels		
Other			15	Barrels		

Description of Other Released Contaminant:

Other recovered substance-rainwater

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Closed valve to isolate leak. Replaced water dump valve.

Wastes Disposal Location: Facility water tank

Agencies Involved: NDIC Oil & Gas

Updates

Date: 6/22/2017 ***Status:*** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary this spill remained on location. NDIC retains oversight.